



Remler Model 72

Restoration Project

Elmo Giovannetti

January 2012

Remler Model # 72 Initial Conditions

The initial condition of the radio is itemized below. Initial condition photos immediately follow along with before and after restoration photos and comments.

Chassis Restoration

1. All tubes missing.
2. Power transformer missing.
3. Speaker missing.
4. Output transformer missing.
5. Power supply inductor missing.
6. Rectifier tube socket needs replacement.
7. Broken lug strip.
8. Many wires under chassis are cut.
9. Power supply: 1 capacitor bad, the other missing.
10. Dial lamps: socket, lamp, and wiring missing. Mounts need alignment.
11. Tuning eye: tube & socket missing. All associated wiring had been removed.
12. Tuning capacitor very tight, needs serious cleaning.
13. Scale & dial mechanism: scale needs replacement. Mechanism stiff and missing parts.
14. Chassis needs cleaning and painting.
15. General troubleshooting and repair.

Cabinet Restoration

1. Cabinet needs refinishing.
2. Both back lower cabinet corners have split apart.
3. Veneer on top of cabinet split and lifting off.
4. Grill Cloth needs replacement
5. Bezel looks bad. Had been painted.
6. Wooden grill broken away from cabinet and one grill element missing.
7. Veneer on right side of cabinet damaged and small piece missing.
8. All user control knobs are missing.

Initial Condition Photos



General Condition Front View



General Condition Back View



Split Back Left Corner



Split Back Left Corner



Split Back Right Corner



Broken Loose Grill Element


Initial Condition Photos



Missing Grill Elements




Dial Mechanism & Scale




Broken Rectifier Socket



No PWR Transformer - Missing Cap




Cut Wires under Chassis



No Speaker No Tubes


Initial Condition Photos




Pilot Lamps & Tuning Indicator




Broken Lug Strip Under Chassis



Broken Lug Strip Under Chassis



Bad Connection & Soldering




Cut Wires Under Chassis

Tubes

One of the initial conditions was that all nine of the tubes were missing from the chassis. Replacements were not hard to find. Six were found in my personal tube collection and three were found in the CHRS collection. In staying with a restoration goal of "as original as possible" the tubes were replaced with metal shield types as implied in the tube inventory list that is printed on the schematic. The tubes were tested and found to be in good condition.

Tube Photos



Tubes Missing



Tubes Replaced

Power Transformer

After looking through many transformers in my collection and at CHRS it became apparent that I was going to have to buy a transformer. Locating a suitable power transformer was made easy by the huge selection of transformers available though Hammond Electric. Sizing the transformer for the 5 and 6-volt supply was straightforward. The high voltage required some adjustment as the replacement speaker I was going to use has an inductor with more than double the resistance of the original. The transformer I used is a Model 276X (640 VCT @173ma. 5 VCT @ 3A. 6.3VC @ 5A.)

Power Transformer Photos



Missing PWR Transformer



Installed PWR Transformer

Speaker, Inductor, and Output Transformer

Locating a speaker that physically fit, has a suitable power supply inductor, hum bucking coil and output transformer proved to be a challenge. Luck turned my way when another CHRS member, Larry Drees, spotted a speaker on line that he thought might be what I was looking for. The speaker looked like a great possibility and after talking to the seller, I concluded that I wasn't going to find anything that would come as close to original as what he was selling. The replacement speaker had two issues: The chassis would have to be slightly relieved to accommodate proper mounting and in addition, the power supply inductor resistance is 2.5 times the resistance of the original.

With only a little cutting and shaping of the chassis the speaker fit perfectly into position.

I needed the inductor resistance to be in the 1K-ohm range. The inductor I was using is 2.5K. The first attempt was to shunt the coil with a 2.0k resistor. I was not happy with this, as the power dissipation of the inductor was about 6 watts. What worked the best was to series a 560-ohm and a 700-ohm resistor and shunt the 700-ohm resistor with the inductor. This lowered the power dissipation of the inductor to approx. 1.5 watts and had little affect on the operation of the radio.

The surprise issue was with the output transformer. If you look at the output transformer on the schematic without looking at the rest of the circuit you can conclude a class A output amplifier. When I connected the speaker and things weren't right I then found the output amp to be class AB and that the schematic was in error, missing the center tap connection to B+. I resolved the output transformer issue by adapting an output transformer I had on hand. For the fun of it, I checked at least three other sets of Riders and found the same omission in all of them. I don't know who to send the correction to.

Speaker Photo(s)




Speaker Missing



Chassis relieved to Accommodate New Speaker

Speaker Photo (s)



New Speaker Installed

Damaged Rectifier Socket

The photos show the steps taken to replace the damaged rectifier socket.

Damaged Rectifier Socket Photos




Damaged Socket



Removing Socket



Socket Removed



New socket installed & wired

Broken Lug Strip

The repairs and replacement of the broken lug strip are shown in the following photos.


Broken Lug Strip Photos



Broken Lug Strip



Broken Lug Strip



Lug Strip Replaced

Cut and/or Missing Wires

The photos show the many cut wires under the chassis. Wires that were cut included: all power transformer leads, speaker and Inductor, dial lamps, rectifier circuit, tuning eye circuit, grid cap circuit, power cord and power switch connections.


Cut and/or Missing Wires Photos



Cut Wires Under Chassis




Cut Wires Under Chassis



Cut Wires Under Chassis



Cut Wires Under Chassis



Wires Identified & Reconnected

Power Supply Capacitor Reconstruction

The major components of the power supply in this radio were missing. This includes the power supply capacitors. One of the filters was missing. The remaining capacitor was unusable. After finding a suitable replacement I decided to empty the containers and replace the innards with axial lead 22 mf 450v caps.

The capacitors were opened by grinding away the crimp at the top of the container. The contents were removed by pushing out the old capacitor through the electrode connection at the bottom. I then washed out the container with Chem-Tool to remove the residual goo. After collecting up the necessary screws, washers, lugs and insulators I assembled the caps and epoxied the top back onto the container.

Power Supply Capacitor Reconstruction Photos



One Missing & One Very Bad Capacitor



Capacitor Ready for assembly



New Capacitor Installed in Can



Both Rebuilt Caps Installed

Dial Lamps

The dial lamp wiring in this radio was missing as well as one of the lamp sockets. The lamp holder bars were bent and coming loose from the chassis. Found a replacement socket straightened and resoldered the holders to the chassis. Rewired the sockets and replace the lamps. I kept with the original screw base # 40 lamp.

Dial Lamps Photos



Pilot lamp missing bracket bent




Pilot lamps restored


Tuning Eye Wiring & Socket Missing

The tuning eye circuit had been completely removed from the chassis. The only part left was the bracket that held the 6U5 in place behind the dial scale. I gathered the components I needed (6U5, socket assembly, period wire, and resistor) from both my collection and from CHRS. I soldered the resistor and wires to the socket then wired the indicator assembly back into the chassis circuitry.

Tuning Eye Wiring & Socket Missing Photos




Tuning Eye missing



Entire Eye circuit had been removed



Tuning Eye Circuit Rebuilt




Tuning Eye wires under Chassis (Tie Wrap)


Tuning Capacitor Cleaning

The tuning capacitor was electrically operational with no bent plates but was difficult to turn. The pictures show it was in need of cleaning. I removed the rotor, disassembled the drive mechanism, cleaned, lubed and reassembled.

Tuning Capacitor Cleaning Photos



Dirty Tuning Capacitor



Capacitor disassembled



Dirty Rotor



Disassembled Rotor Drive



Capacitor Cleaning



Capacitor Drying

Tuning Capacitor Cleaning Photos



Cleaned Capacitor Installed

Scale & Dial Mechanism

The scale and dial mechanism on this radio had problems. The back of the dial scale had been painted with a black opaque paint and was flaking. The cursor had been broken off of the shuttle, the dial cord was missing, the dial chord pulleys were stiff, and the concentric tuning shafts were gummed up. I was fortunate to find a soft copy of the dial scale graphics for the model 72 and had *Fast Signs* print this image as a decal. I then applied the decal to a cut to size clear piece of acrylic and reassembled the scale frame. The broken off cursor was fixed by using a 4" X 1/8" piece of acrylic rod. I shaped the end to fit into the shuttle then dyed the rod using a red sharpie. Replacing the dial cord was fun. I purchased 6 feet of cord, found a spring and figured out how to thread the mechanism. Another issue was that the dial cord pulleys were stiff with one being almost frozen. Using different solvents, *Brasso* and elbow grease I was able to free up the pulleys without having to remove them. The last issue with this mechanism was that the concentric tuning shafts were gummed up. I was able to separate the shafts and thoroughly clean the ball bearings, raceway and shafts.

Scale & Dial Mechanism Photos



Dial Cord Missing & Broken Cursor



Bad Condition Of Dial Scale



New Cursor and Painted Shuttle



Gummed up Tuning Shafts

Dial & dial Mechanism Photos



Tuning Mechanism Restored

Chassis Cleaning & Painting

As the pictures show this chassis had seen better days. I started by washing the chassis. I removed the tuning coil and IF cans and any other sensitive components. I protected the coils by putting them in plastic bags and sealed them the best I could. I then sprayed the top and bottom of the chassis with *Super Clean* then lightly hosed it off. The amount of grime removed was impressive. I dried the chassis using low-pressure compressed air and the sun. Repainting the chassis was the next step. The original finish was a gray wrinkle paint that was not available. What I did use was a black wrinkle paint which I used as an under coat then applied a gray topcoat finish. In order to avoid painting the tube socket rivets or having to drill them out I put a drop of wood glue on each rivet head. After painting, the glue was easily removed with an exacto knife.


Chassis Cleaning & Painting Photos



Chassis being prep for painting



Chassis being prep for painting




Chassis being prep for painting



Chassis being prep for painting

Chassis Cleaning & Painting Photos



Chassis being prep for painting



Chassis painted



Chassis painting completed



Chassis restored

General Repairs And Troubleshooting

Before serious troubleshooting or applying power to the radio, the broken rectifier socket and lug strip needed to be replaced. Also, all of the dangling wires needed to be identified and documented.

After these repairs, I inspected the chassis for obvious problems and did some continuity testing. After clearing a short in the 6.3 v circuit and removing the totally bad filter capacitor I began troubleshooting.

At this point I had not yet located all the components I needed to start reassembly. I needed to get started on troubleshooting and repair so I decided to rough together a power supply on the bench and use clip leads to connect power and other components to the chassis.

After the components were connected, I applied power using a variac to control the input voltage. Slowly, increasing the input voltage, I measured the 5, 6 and 620 secondary volts to make sure they were rising with the increase in input voltage. At 110 Volts the tubes were heated up but the B+ supply was only about half of what it should be. There was nothing coming from the speaker.

I began troubleshooting at the audio amplifier. The test equipment used was a DVM, signal generator (audio & RF) and oscilloscope.

The problems found were:

1. The before mentioned output transformer center tap issue.
2. Four capacitors were found to be bad and were replaced (C31, C32, C34, & C40). In my collection of vintage capacitors I found three replacements that were electrically the same and tested good for both capacity and leakage. Although these capacitors tested good they looked terrible. I cleaned them up by re-waxing them. I first brushed off the old wax after heating with a heat gun then dipped them into clear wax.
3. A very intermittent volume potentiometer, which I disassembled and cleaned.

After resolving these issues the amplifier worked fine but still no signal through the radio.


After not finding a signal at the detector, IF stage, and no local oscillator, I began to look into the oscillator circuit.

In troubleshooting the oscillator the test equipment used was a DVM and oscilloscope. Performed a continuity test on the oscillator coils. To my relief no opens were found. Further troubleshooting revealed the following:


1. A very dirty band selection switch.
2. A broken wire on the last wafer of the band selector switch.

After resolving these issues the oscillator was working but at too high of a frequency. What should have been an obvious solution got confused into a search for something that was not broken. Finally, when I put the band selector switch in the broadcast position things began to work.


General Repair Photos




General Troubleshooting




General Troubleshooting




General Troubleshooting



General Troubleshooting




General Troubleshooting



General Troubleshooting

General Repair Photos




General Troubleshooting



Replacement Capacitors before re-waxing



Removing old wax



Re-waxing capacitors in clear wax



Finding vintage capacitors, that tested good, in my parts collection was a great find. They kept the underside of the chassis looking authentic and saved me from the messy and time consuming job of re-stuffing the defective ones. I also got pleasure, putting parts that have been on the shelf for years, back into service.

Refinishing Cabinet

Don't know the history of this radio but it looked like at some time someone refinished the cabinet with an orange/reddish finish. Not sure what the finish actually was, but it was difficult to remove. In fact, I was never able to completely remove it. After using lacquer thinner, multiple applications of paint remover, sandpaper and steel wool, enough of the old finish had been removed so that the new finish could be applied. To help prevent blotchiness, I first applied a pre-stain wood conditioner followed by the finish stain. The stain used is a *Minwax Red Mahogany*. After a few days of drying I hand waxed the cabinet with *Minwax Paste Finishing Wax*.

Refinishing Cabinet Photos



Initial Condition



Cabinet Stripping



Cabinet Stripping



Cabinet Stripping



Cabinet Stripping

Refinishing Cabinet Photos



Cabinet Sanding



Completed Cabinet

Cabinet Repair Back corners

The two lower back corners of the cabinet had pulled away from the cabinet base. To repair this, I screwed two wooden runners to the inside base of the cabinet on the left and right sides. I then peeled back the veneer on both sides of the cabinet applied glue, compressed the joints then put screws through the sides of the cabinet into the runners. The final step was to glue the veneer back into place.

Cabinet Repair Back Right Corner Photos



Back right Corner Split



Back Bottom Right Runner



Back Right corner Screws



Back Right Corner Repair

Cabinet Repair Back Left Corner Photos



Back Left corner Split



Left Corner Runner



Back Left Corner Screws



Back Left Corner Repair

Cabinet Repair Top veneer Repair

On the top of the cabinet the veneer had split and began to de-laminate. This as well as other problems with the veneer and finish led me to believe that the cabinet and chassis had been exposed to water. To correct this problem, I injected glue under the veneer pushed it down into position then clamped it in place over night.

Cabinet Repair Top veneer Repair Photos




Cabinet Top Veneer Damage



Cabinet Top Veneer Repair



Cabinet Top Veneer Repair



Cabinet Top Refinished

Grill Cloth Replacement

The grill cloth that had been replaced sometime in the history of this radio gave the set a festive look but didn't seem period appropriate. On line my wife found a site that had a great selection of grill cloths. We picked one that we liked that complemented the cabinet.

Grill Cloth replacement Photos



Initial Grill Cloth



New Grill Cloth

Bezel

At sometime the bezel had been painted black. The paint was thick and not evenly applied. After giving some thought on how to remove the paint, I decided to test the bezel material to see if it could withstand paint remover. Much to my surprise the paint remover did not attack the plastic like material. After removing the paint and polishing the bezel, I replaced the missing window with a piece of 1/16" thick acrylic plastic. The final touch was to put gold leaf tape into the trim along the sides of the window.

Bezel Photos



Painted Over Bezel



Restored Bezel

Wooden Speaker Grill

The wooden speaker grill had suffered some damage over the years. One of the 5 horizontal elements was missing; another had broken loose from the cabinet on the right side. The others were barely attached.

In order to replace the missing element, I had to fabricate one. I took one of the grill pieces to a local woodworking shop and tried to match the wood species. I found a piece that closely matched the grain and density of my sample. I then traced the outline of my sample on to the wood and did a rough cut out using a band saw. I contoured the piece to shape using a wood rasp, electric sander and sandpaper.

My final step was to attach the grill pieces to the cabinet, equally spacing them. I used small finishing nails and wood glue to secure them.

Wooden Speaker Grill Photos



Initial Condition




Initial Condition



Stripped Grill Elements



Positioning Grill Elements



Fabrication a Grill Element

Wooden Speaker Grill Photos



Restored Grill

Back Left Side Veneer Repair

On the back left side of the cabinet the veneer had been damaged. The only way to repair it was to cut out the bad sections and replace them. I found usable pieces of veneer that closely matched the cabinet at CHRIS. I then removed the damaged veneer from the cabinet. I matched the grain, sanded and fitted the pieces together. I glued them into position and clamped them overnight. The following day I removed clamps trimmed the pieces and sanded the matching joints.

Back Left Side Veneer Repair Photos



Damaged Veneer



Damaged Veneer Replaced



Damaged Veneer



Damaged Veneer Removed

Back Left Side Veneer Repair Photos



Replacement Veneer Pieces



Replacement Veneer Glued



Veneer Replaced & Finished



Veneer Replaced & Finished

Missing knobs

One of the initial conditions was that all five knobs were missing from the radio. I was fortunate that a fellow CHRS member, Jamie Arbona, has a complete Model 72. Jamie was kind enough to allow me to use his knobs as masters for duplication. Jamie referred me to Larry Bordonaro who had previously cast knobs for other CHRS members. Unfortunately, when I contacted him, he had given up reproducing knobs due to health issues. I then searched the Internet looking for someone that could do castings. Again, I was fortunate that I found someone locally that was in the business of mould making and casting. It took less than a week and I had the replacement knobs I needed.

Missing knobs photos



Initial condition no knobs



New Knobs Installed



Remler Model 72

Completed Restoration

Elmo Giovannetti

January 2013

REMLER COMPANY, LTD.

MODEL 72
 Reg. Ser. 104459
 Schematic, Voltage
 Alignment, Data

SERVICE DATA

The following tubes are used in this receiver:

- 1 6X7 R.F. Amplifier
- 1 6L7 Mixer
- 1 6K9 Oscillator
- 1 6E7 I.F. Amplifier
- 1 6X4 Diode Detector
- 1 6V7 A.F. Amplifier
- 1 6P6 Power Amplifier
- 1 6Q5 Tuning Indicator
- 1 5Z4 Full-wave Rectifier

The R.F. Mixer and Oscillator coils are located in the square shields on the right end of the chassis. Trimmers for these circuits are mounted along the end of the chassis in the following order from front to rear: R.F. short-wave, Mixer short-wave, Oscillator broadcast, Oscillator medium wave, Oscillator short-wave. The R.F. broadcast and the Mixer broadcast trimmers are mounted on the band switch assembly.


Oscillator pads are located at the rear of the chassis. The broadcast pad is nearest the end of the chassis and the medium wave next.

Trimmers for the I.F. transformers are adjustable thru holes in the I.F. transformer shield cans. The I.F. frequency is 450 K.C.

A.C. Voltages		180 Volts
Line	Heater 5Z4 rectifier	5.00
	Other heaters	6.00

D.C. Voltages		240 Volts
From ground to:-		
5Z4 Rectifier		240
6P6 Plate		225
6P6 Screen		240
6P6 Bias supply		17.5
6V7 audio plate		130
6V7 Bias		-5
6E7 I.F. plate		240
6E7 I.F. screen		240
6E7 I.F. grid bias		-4.5
6K9 Mixer plate		240
6L7 Mixer screen		160
6L7 Mixer grid bias		-4.5
6E7 A.F. plate		240
6E7 A.F. screen		180
6E7 A.F. grid bias		-4.5
6Q5 Oscillator plate		150
6Q5 Tuning Indicator plate		240

Readings taken with 1000 ohm per volt meter.



TUNING RANGE
 The lower scale of figures on the dial is the calibration for the broadcast range which extends from 240 to 1310 kilocycles. The medium wave range is indicated by the middle scale of figures which are colored green. This range covers from 1.7 megacycles to 3.7 megacycles and includes the amateur, police and aircraft bands. The upper red scale is the short-wave range and extends from 5.7 to 18 megacycles. The various foreign and American short-wave broadcast bands are included in this range and are marked by the inscriptions on the dial.

OPERATION
 With the line plug connected, turn the volume control to the right, the dial should light up brightly. On some sets, a switch on the right side of the case may be used to turn the volume control to the left. For best quality the selector should be adjusted for minimum shadow on the tuning indicator which is located in the center of the dial.

MODEL 72

This is a ten tube all-wave receiver with metal tubes. It is designed to operate from a 110 to 125 volt, 50 or 60 cycle power supply.

INSTALLATION

When a standard antenna is used, the length should be from 25 to 100 feet. Connect to the thin wire extending from the back of the receiver. The antenna lead-in should be kept away from all metal objects such as pipes and wires, so should be run in as straight a line as possible. An indoor antenna may be used for local reception or when the receiver is used in an isolated wooden building. Superior performance on short wave will result from the use of a well constructed doublet antenna, or short wave antenna system. Such antennas are available on the market in kit form with complete instructions for their installation.
 A good ground is essential for clearest reception. Connect the black wire to a water or meter pipe. The pipe should be stripped clean before attaching the wire.

RESISTORS	CONVERTER
1 20 Ohms	1000000 mV
2 100	100000
3 150	10000
4 20000	1000
5 10000	100
6 15000	10
7 10000	1
8 50000	0.1
9 100000	0.01
10 1000000	0.001
11 1000000	0.0001
12 1000000	0.00001
13 1000000	0.000001
14 1000000	0.0000001
15 1000000	0.00000001
16 1000000	0.000000001
17 1000000	0.0000000001
18 1000000	0.00000000001
19 1000000	0.000000000001
20 1000000	0.0000000000001
21 1000000	0.00000000000001
22 1000000	0.000000000000001
23 1000000	0.0000000000000001
24 1000000	0.00000000000000001
25 1000000	0.000000000000000001
26 1000000	0.0000000000000000001
27 1000000	0.00000000000000000001
28 1000000	0.000000000000000000001
29 1000000	0.0000000000000000000001
30 1000000	0.00000000000000000000001

REMLER COMPANY, LTD.

MODEL 72
Reg. Ser. 104459
Schematic, Voltage
Alignment, Data

SERVICE DATA

The following tubes are used in this receiver:

- 1 6X7 R.F. Amplifier
- 1 6X5 Mixer
- 1 6Z5 Oscillator
- 1 6BT I.F. Amplifier
- 1 6BE Diode Detector
- 1 6BT A.F. Amplifier
- 1 6BE Power Amplifier
- 1 6Q5 Tuning Indicator
- 1 5Y4 Full-wave Rectifier

The R.F. mixer and oscillator coils are located in the spare shields on the right end of the chassis. Trimmers for these circuits are mounted along the end of the chassis in the following order from front to rear: R.F. short-wave, mixer short-wave, oscillator broadcast, oscillator medium wave, oscillator short-wave. The A.F. broadcast and the mixer broadcast trimmers are mounted on the head switch assembly.

Oscillator pads are located at the rear of the chassis. The broadcast pad is located the end of the chassis and the medium wave 200K.


Trimmers for the I.F. transformers are adjustable thru holes in the I.F. transformer shield case. The I.F. frequency is 450 K.C.

A.C. Voltages

Line	250 Volts
5Y4-5Y4 Rectifier	250 "
Other heaters	4.00 "

D.C. Voltages

From ground to:-		250 Volts
5Y4 Rectifier	250	250
6BE Plate	250	250
6BE Screen	250	250
6BE Aline supply	17.5	17.5
6BT audio plate	150	150
6BT bias	0	0
6BT I.F. plate	250	250
6BT I.F. screen	150	150
6BT I.F. grid bias	-1.5	-1.5
6Z5 screen plate	250	250
6Z5 mixer screen	150	150
6Z5 mixer grid bias	-1.5	-1.5
6BT A.F. plate	250	250
6BT A.F. screen	150	150
6BT A.F. grid bias	-1.5	-1.5
6Q5 Oscillator plate	150	150
6Q5 Tuning indicator plate	250	250



Headings taken with 1000 ohm per volt meter.

SERVICEMAN
The lower scale of frequencies on the dial is the calibration for the broadcast band which extends from 510 to 1510 kilocycles. The medium wave range is indicated by the middle scale of frequencies which are indicated by this range covers from 1.7 megacycles to 2.7 megacycles and includes the amateur, police and aircraft bands. The upper scale is the short-wave broadcast band which extends from 1.5 to 15 megacycles. The American short-wave broadcast bands are indicated at 1500 KHz and are identical to the international standard.

SERVICEMAN
When a standard antenna is used, the length should be from 25 to 100 feet. Connect to the main wire extending from the back of the receiver. The antenna lead-in should be kept clear of all metal objects, such as pipes and wires, as should be run in as straight a line as possible. An indoor antenna should be attached to the receiver as shown in the diagram. If an outdoor antenna is used, the antenna should be attached to the receiver as shown in the diagram. The antenna should be attached to the receiver as shown in the diagram. The antenna should be attached to the receiver as shown in the diagram.

SERVICEMAN
The line cord connected, turn the volume control to the right, the dial should light up brightly. Allow the speaker to operate for 15 to 20 minutes. The volume control should be turned to the right until the speaker is just barely audible. The volume control should be turned to the right until the speaker is just barely audible. The volume control should be turned to the right until the speaker is just barely audible. The volume control should be turned to the right until the speaker is just barely audible.

SERVICEMAN
This is a 100 watt, all-wave receiver with metal tubes. It is designed to operate from a 110 to 125 volt, 60 or 50 cycle power supply.
MODEL 72
When a standard antenna is used, the length should be from 25 to 100 feet. Connect to the main wire extending from the back of the receiver. The antenna lead-in should be kept clear of all metal objects, such as pipes and wires, as should be run in as straight a line as possible. An indoor antenna should be attached to the receiver as shown in the diagram. If an outdoor antenna is used, the antenna should be attached to the receiver as shown in the diagram. The antenna should be attached to the receiver as shown in the diagram. The antenna should be attached to the receiver as shown in the diagram.

6C5
0

FRONT




4H6 6K7 6L7 6K7
0 0 0 0

500,000

6F6 6F6 6N7
0 0 0

6Z4
0

300,000



Filaments - 6.3V

- ✓ ① Chassis GND
- ✓ ② Pin 7 of 6F6-1

6C5

Fil 1#6

Gnd 3

Plate 2

- ✓ B+
- ✓ GND - Junction R1 & R2
- ✓ B+ - Pin 4 of 6F6 - Cap 46

Plate 4

Cathode 5

Wire ID's

#1 - Pin 2 6F6-1 - Fil GND for eye tube #pin 1

#2 Pin 7 6F6-1 - Fil supply for eye tube - Also Fil supply input from X former.

#3 Pin #4 6F6-2 B+ for eye tube (pin #4) Target

#4 Junctions R1 - R2 - Cathode of eye tube Pin #5


#5 Pin #3 6H6 - Gnd of eye tube pin 3

3-30-12

e

Rectifier Analysis - 5Z4



* Variac Controlled
Line Volts 120




① Rectifier output $\frac{376}{395V} - SB 340V$

② output of filter $\frac{164V}{268} - SB 240V \quad 125V \quad \textcircled{2}$

Power trans - Triad # R-115A




Ideal outputs
630 ct - 315-315 ct
@ 100mA
5V @ 2.5 Amp
6.3V @ 4.5 Amp



6.3V
@ 2.5 Amp

5.79V @ 3.7A

$$\frac{+6}{4.3}$$



5V @ 2.5 Amp 4.8V @ 2A

Red - measured values

Notes:


- ① 6.3V overloaded - this measurement does not include Pilot lamp & 665 Filament currents
- ② 665 - Heater 6.3V @ .3Amp
- ③ #4 Pilot lamps = 6.3V @ .150amp

Possible Replacement transformers


① www.hammondmfg.com/23263.htm

#276X - 640 ct - 5V ct - 6.3 ct
172mA 3A 5A

5WLS, C



$$\frac{134}{110} = 244$$



$$\frac{184.6}{55.38} = 22398$$

$$Z_c = 127 \Omega$$

2.8V

$$I = \frac{240}{68K} = 0.003529$$


$$E = I \cdot R = 17K \cdot I = 17000 \cdot 0.003529 = 59.993$$

2.4V

105A

I = .023a

$$E = I \cdot R = 0.023 \cdot 51K = 1173$$



$$X_c = 2\pi fL$$

#4 .15uF

665 Hertz @ 6.3V

.6amps

$$122^2 + 122^2 = 122^2$$

$$G^2 = 122^2 + 122^2$$

$$I = \frac{240}{65K} = 3.692$$

$$\frac{136}{113} = 249$$

14884

R7 = 15K C39 = .1uF 400V


R10 = 50K

To Look at:

- ① Determine ideal DWR & Formae -
- ② Are Voltages better when B+ is set at 240? - Yes!
- ③ Check out low screen volts on 6K7-IF, 6L7, 6K7-RF (R7, R10, C39)
- ④ Check 6K7-RF Bias ckt -


3-30-12

Audio Output Analysis - 6F6





① Are both tubes driving the output transformer? Yes

②



output Xformer # 70-110




Turns Ratio

24/1

76/1


40/1

DCR - Speaker coil
 $\approx 6.0\Omega$
 $(1.25)(6) = 8\Omega$



Pri. Sect


43.0	-	1	Bl. - yell	= 14729
30.2	-	1	Bl. - Green	7296
21.6	-	1	Bl. - Orange	3732



$(X^2)(8) = 10K$
 $X^2 = \frac{10K}{8}$
 $X^2 = 1250$
 $X = \sqrt{1250} =$
 $X = 36\Omega$ $t_n = 36-1$

$\sqrt{\text{Turns Ratio}} = 2$

$\% \text{ D.P.} = T R^2$



Bottom View

$$\begin{array}{r} 1560 \\ 450 \\ \hline 1010 \end{array}$$




$$\begin{array}{r} 650 \\ 450 \\ \hline 1100 \end{array}$$

c




fully closed 486.66 KHz

IF - Plate of 6L7 pin 3 - input
Grid of 6K7 - out

Front







1024.6



$$R_T = 543$$

$$\frac{560}{1103}$$






1-30-12

✓


Lug Strip Replacement

Original




#1 - Blank

#2 -




#3



#4 - ? missing (Think not used, Separation of PWR CKT)

#5



#6

Grounded



✓