FAIRBANKS~ MORSE 1938 RADIO RESTORATION – Model # 5-C CALIFORNIA HISTORICAL RADIO SOCIETY

International Radio Restoration Contest Entry

March 15th 2014

Restoration by: Cliff Farwell
This was a radio that I purchased for parts only.

It was in such poor condition and my objective was to obtain parts for another radio. After joining CHRS and learning more about these timeless treasures I decided to take this old radio and restore it to the best of my ability and enter your competition.

I started with the mechanics as this radio was not in working condition. I have compiled some photos that I took during the restoration. I have noted next to each photo what I had done to bring this radio back to life. It was been a lot of work but I feel the end result speaks volumes.




This is the initial condition of the cabinet and degraded dial cover. Note the shredded speaker cloth below my hand.



This is what the chassis looked like before restoration, with heavy corrosion.



This is the initial condition of the speaker found in the cabinet, obviously inoperable!



Here you see the shadow from the dial housing which has been removed along with the broken dial belt. A new belt was later installed.



In this photo, the chassis is being stripped of old paint and rust. The old power transformer was found to have an open primary winding and removed.



The tuning capacitor was subsequently removed and cleaned, to be re-installed after the chassis was cleaned and repainted. New tuner grommets were installed.



The rusted dial face housing and the old dial belt were removed for repainting and replacement.



After bead blasting the dial face housing was repainted with a satin white paint as per original including mounting screws.

The old rubber dial housing light grommets were replaced with new as shown in photo.



The speaker was rusted with the cone torn out. The spider remained intact but later replaced with NOS (New Old Stock). Fortunately, the speaker voice coil and transformer were tested and found in good condition.



The speaker coil & transformer leads were wired tagged for future reference.



I sand blasted the speaker frame at a local engine machine Shop. I then repainted the speaker frame prior to cone repair.





Speaker basket repainted. Transformer re-installed and speaker re-coned. A new spider was installed, sourced from NOS (New Old Stock).



Final step: Speaker gasket added to match original.



Painting, as with entire restoration was done by myself. An Awata spray gun was used to apply SEM etching primer and OMNI copper metallic matched paint. The new paint was color matched by a local auto body supply shop for the chassis finished coat.

I replaced the original power transformer with a replacement from the Antique Radio Supplies. The power cord was replaced with a gold cloth covered cord with a reproduction Bakelite plug.




The tube shields were bead blasted as well and coated with a 1200* ceramic coating for heat and rust resistance. This was matched to the original metallic look.



After the tube shields were coated they were placed back into position covering the designated tubes.

False, "dummy "electrolytic filter capacitors cans were made for authentic appearance. They were stuffed with modern electrolytic capacitors. These housings are made of copper for grounding conductivity, and then wrapped with black insulating paper.



Close size match; new power pransformer next to original



Damaged exposed wires were replaced with reproduction insulated cloth covered wires. (Sundial Antique Wire Co.)

All electrical contacts were cleaned with electrical safe CRC solvent. The new power transformer was installed and tested with the rectifier 5Y3G tube removed. A 60 watt bulb was placed in series with the primary for initial testing.

The old capacitors & electrolytics were all replaced with new ones. All resistors were checked and passed the manufacturer specifications.




All tubes were tested with a Hickok tube tester. I discovered that several tubes needed to be replaced.




I am pointing to the rivets that I had to reproduce in order to secure the dial face. These were not salvageable or obtainable.



The old damaged dial face was replaced with a new reproduction made by Radio Graphics. The dial lights were rewired and the dial lights were replaced. The face was installed using machine screws and the heads were filed down as per old rivets to give a tight fit to the new dial face cover once the chassis was installed. I had also installed a new belt prior to the dial face being secured.



Before



Replica





The tube diagram decal for the Fairbanks Morse 5C was removed for the chassis restoration.

The Replicas were made by Graphics Radio




There were several steps to re-facing the body of this radio. The veneers were broken and chipped in many areas. The inside of the unit had a wasp nest, mud and had water damage.

I bleached the cabinet and stripped the inside and outside.



The cabinet needed to be resurfaced with new veneer and the under ply repaired. Both lower and right corners were severely damaged. The photos enclosed will show the process from beginning to end.



The lower corners were damaged on the face. The side panels required minimal veneer replacement.

The missing pieces were blended in with new veneers.

The front veneer had separated from the cabinet top as shown in the photo.



The interior of the cabinet had begun to separate. After the chassis was removed several wasp mud nests were revealed. A round slow speed wire brush was used to remove the wasp nests.



The cabinet base runners were secured and gluded and the old glides were removed and replaced with new glides.

The cabinet side ply's were re-glued and clamped to the cabinet base. I then sanded and refinished the outside bottom of the cabinet.





The interior seams were re-gluded on all sides including all corner reinforcement blocks. I completed the interior by sanding and refinishing with a coat of stain.



The existing front top ply was then clamped and re-gluded.



The veneer was so badly damaged that I decided to reface the cabinet. I choose a Fancy face crotch mahogany veneer that matched the original face pattern.

After the underlayment and old veneer was repaired, I applied Tie Bond III glue to both cabinet face and veneer and secured with a hot wood iron.



The new veneer I used was from Sauers & Co. processed veneer. This was a Crotch Mahogany book mark matched. I have included an unfinished sample below.





Once the veneer was secured to the face the radio I began the slow and tedious process of cutting the dial face, grill and chassis holes. This was very time consuming. I used a Dremel hand router with cutting and sanding bits.







The photographs on this page show the progressive cutting of the veneer to the original radio face cut outs.

There were several natural cracks in the veneer in which I filled and sanded. This took many steps to smooth out the surface.





I used a pine 1×4 as a jig guide for my Dremel router. The design grooves on the base and front of the cabinet face had to be hand cut with router to replicate the original design of the cabinet.



After routing the new grove lines into the new veneered face, and application of black lacquer to highlight.



I applied a brown cordovan toner to the two parallel grill frames as per original color scheme.





The feet were glued and air gun nailed into position. Luckily I found the feet lying inside the cabinet.



The cabinet was sanded with 320 grit Norton sand paper.

An application of Mohawk grain filler was used to soften the pores of the wood prior to applying the lacquer finish. (Mohawk Lacquer).

Toners were used to blend the cabinet face into the old existing veneer.








Upon completion of spraying several coats of sanding sealer and satin lacquer, each coat was hand sanded. This took approx. 8 coats.

The final coat was rubbed out with rottenstone compound and light 3-1 oil. I found a chalk board eraser worker well. This helped give it a nice even finish.





The old grill cloth was totally destroyed. I constructed a new backer board, using the old one as a pattern and replaced the grill cloth.





The speaker grill cloth was attached to a thin plywood backer-board with spray adhesive. The ply was cut by hand and fit to the cabinet as per original. Staples secure it in place.

I then secured the dial face cover after the brass escutcheon trim in place.

Awaiting the chassis, the cabinet is finished. The speaker grill cloth installed, escutcheon tacked in place with brass nails.



Chassis now completed, speaker re-coned and tested. Cabinet is repaired and refinished.





Cabinet ready for chassis installation



Cabinet complete, speaker is mounted and connected to the chassis circuit. Chassis is mounted with new grommets and bolted to the cabinet using original screw bolts. Decal has been replaced.



The missing knobs were found via the Antique Radio Forum and I purchased from a member. The knobs are backed with felt washer. Rosette screws were purchased from ANTIQUE RADIO SUPPLIES to secure the speaker as per original.

I aligned the radio at KRE (CHRS Headquarters), IFs at 456 KC as per the alignment instructions by the manufacturer.

This information was found Via the RIDER publications volume VIII Page 8-2 Fair –Morse Models 5C-6A




FINAL ASSEMBLY~ The Radio is completed!

RESTORATION: Dec 7th 2013

REFERENCES & RESOURCES

Rider Publications Hickock Tube Testers Antique Electronic Supplies U.S. Art Supply Rockler Wood Working Radio Graphics Radio Daze Antique Radio Forum-Barry McDonald Renovation Radio Sundial Antique Wire Supplies Just Radio's The Speaker Shop Mohawk Finishing Supplies Neds Auto Body Supplies Martinez Engine & Machine CHRS Workshop at KRE Decals by Radio Daze



PAGE 8-2 FAIR-MORSE

DODELS SC, GA Alignment, Voltage Resistance

FAIRBANKS, MORSE & CO.

ALIGNMENT

The models 3C and 6A are AC operated, superheatendese chasses with automotic volunto custrol. These receives operate on three bands—bloodcast, police sensiture, and short wore, Figure 4. The 6A has the tuning eye, Figures 3 and 4; the 3C does not. Otherwise, the two chasses are identical.


Alignment procedure is given below in chart form, Figures 1 and 2.

Make adjustments in the order given. The corput mater may be any

low engar AC volument, preferably about 9-15 volus. It should be conmerced from the pites of the 65°KG tube to ground with a 1 add, rendenser in series with sea of the lexit. When the hand testit to go off scale, reduce the input from the signal generator and lamp the volume central at maximum. If we enough a signal is fed to the streture and the volume central in used in keep the suspent mater hand on scale, the A. V. C. will operate and incorrects allocations of silication.

| No | Consuction To | Suprai Generator Frequency | Dunny | Range Switch | Diel Setting | Steam | Tripper No. | AFC | Prot For | Special Instructions |
|----|------------------|----------------------------------|-------------------------|--------------------|-----------------|---------------|----------------|-----|-------------|---|
| 1 | KARG GAL | 494 KC | -1 infd. Condenser | Bresdoor | 190 EC | Ind IF | 1. | | Min. | - |
| 1 | KANG GAM | 456 KC | J mfd. Constraint | Bookse | 749 EC | 266 19 | 1 | | Max. | |
| | AARG GHE | who MC | J. mfd. Condense | firedist | 336 KC | In IF | 1 | | Max. | |
| * | AANG GHZ | 436 R.C | J self. Condense | Brudese | 930 KC | te IF | | | Mrs. | |
| 5 | Antenne | 416 KC+ | 600 sinn Resimer | Breedom | 990 EC | Wese Trap | 3 | | Mis. | *Haise inpur up- til rignal in bescot. |
| 6. | Astron | 14 MC | 400 obje Resistor | Peliss Assume | 3,4 MC | Police | | | Max. | beard. |
| 2 | Agreeme | 3.4 MC | 900 alas Racistas | Felice Amereus | 5,4 MC | Policy Dec | 7 | | Man. | |
| | Automa | 7.8 NC | 400 sinn Resistor | Police Acceteor | I.B Sec | Pelin | | | Miles. | White miling |
| 9 | Agressi | 1500 EC | 200 and a Occhomi | Stranfort | 1386 822 | B.C. | | | Mex. | change is some. |
| 10 | Astron | 1100 KC | 300 mmfg. Condenser | Prosient | 1369 EC | 8.0 | 19 | | Mat. | |
| | Aetroso | 680 XC | 200 morid. Grediense | Broadcast | 600 EC | S.C. | 11 | | *Mac. | - Beyon 5, 16 and 11 until so though is noted. |
| 4 | Assess | IN MC | 900 alon. Projetse | Stort Ware | IN NC | E.W. | - 11 | | Man | Street, it same. |
| 9. | Assesse | 18 MC | 600 shin Recent | Stort | 18 MC | S. W. Det. | 15 | | Man. | |
| 14 | Acress | # MC | #00 ulon Recistor | Short Want | # MC | Lett. | , | | | *Check culture. tion at A MC.— Padder is flood. |

FIGURE 2 ALIGNMENT CHART



*CONNECTED TO TARGET THRU I NEGOTIN RESISTOR -- 30 VOLT SCALE *3 VOLT SCALE

VOLTAGE AND RESISTANCE ANALYSIS CHART

John F. Rider, Publisher